



Precision surface. No fingers, please!



For your disk's sake (and the system's, too) insert disk carefully



Magnetic fields erase. Keep them far away.



Keep it safe in the jacket when not in use.



Bending and folding may damage. Handle with care.



Keep disks comfortable. Store at: 10° to 52° C. 50° to 125° F





